

# DURABILITY OF INCRALAC, EXAMINATION OF A TEN YEAR OLD TREATMENT

David Erhardt, Walter Hopwood, Tim Padfield and Nicholas Veloz

## **Abstract**

Ten year old Incralac varnish on four outdoor gold plated bronze statues in Washington, D.C. was found to be cracked and insoluble. The Incralac was removed from the statues by softening with paint remover containing methylene chloride followed by pressurised water spray. In comparison with fresh Incralac, the ultraviolet absorption of the weathered material was greater and the benzotriazole had mostly disappeared. The infrared spectrum was little changed.

*This is a digital version of the article first published as: David Erhardt, Walter Hopwood, Tim Padfield and Nicholas Veloz, 'Durability of Incralac, examination of a ten year old treatment', Preprints, ICOM (International Council of Museums) Conservation Committee, Copenhagen Conference 1984 pp 22.1 – 22.3*

THE DURABILITY OF INCRALAC: EXAMINATION OF A  
TEN YEAR OLD TREATMENT

David Erhardt, Walter Hopwood and Tim Padfield

Conservation Analytical Laboratory  
Smithsonian Institution  
Washington, D.C. 20560 USA

Nicolas F. Veloz

National Capital Parks  
George Washington Memorial Parkway  
c/o Turkey Run Park  
McLean, VA 22101 USA

SUMMARY

Ten year old Inctalac varnish on four outdoor gold plated bronze statues in Washington, D.C. was found to be cracked and insoluble. The Inctalac was removed from the statues by softening with paint remover containing methylene chloride followed by pressurized water spray. In comparison with fresh Inctalac, the ultraviolet absorption of the weathered material was greater and the benzotriazole had mostly disappeared. The infrared spectrum was little changed.

Introduction

Flanking the east end of the Arlington Memorial Bridge and the entrance to Rock Creek Parkway in Washington, D.C. there are four large gold plated bronze statues (Figure 1).



Figure 1 The gilded bronze 'Valor' on the southeast corner of the Arlington Memorial Bridge.

They were put in place in 1951. By 1971 their condition had deteriorated to the point where extensive repair and restoration

was required. Corroded steel bolts, nuts, tie rods and braces were replaced with brass or bronze, accessible residual mould materials, including gypsum and sand, were removed from the interior, and cracks and pits were filled with a tin-silver solder. The original fire gilded surface was entirely removed by sandblasting. The statues were then brush plated with two layers of nickel followed by at least one layer of gold.

The final treatment in 1971 was the application of a coating of Inctalac varnish. The procedure was described by Ogburn, et. al.<sup>1</sup> It is this coat of Inctalac which is the subject of this report.

Condition of the statues in 1983

By 1983 the statues, located within 30 metres of roads carrying over 100,000 vehicles per day and under the flight path of National Airport which handles over 900 flights per day, again needed attention. Nicolas Veloz and other Park Service personnel undertook the treatment. The statues were quite dirty and there were areas of deterioration: deposition of core material, some corrosion around weepholes and seams and apparent loss of detail. Despite their poor appearance, the statues and gold plating were basically in good condition. The Inctalac had failed over virtually all surfaces. There was a darkened, "painted" appearance overall and a grey cloudiness over parts of the statues which was, on closer inspection, found to be due to cracking and breakup of the Inctalac layer (Figure 2). Air under the loosely adherent polygonal plates caused the cloudiness. Loss of Inctalac had left some areas bare. These exposed areas were bright gold. The worst areas were those exposed to both sun and weather. Exposed areas on the north sides had an extensive craquelure, but little loss of Inctalac. Only in sheltered areas did the Inctalac still appear to form a coherent film, but even here there was an invisible craquelure. This was revealed by spotting dilute aqueous sodium carbonate on the lacquer film. Tests showed that electricity could be conducted between the




Figure 2 Fragmentary remnants of Inctalac on the base of 'Valor'. This area is 12 mm across.

lacquer surface and bare metal areas, indicating that the sodium carbonate solution had penetrated the lacquer.

#### The 1983 Treatment

The Inctalac coating proved resistant to solvents and paint strippers which readily dissolve fresh Inctalac. These did not dissolve or emulsify the Inctalac, but they did soften it enough to allow mechanical removal. The method found to be most effective was repeated applications of methylene chloride based paint stripper followed by cold water spray at a line pressure of 6 Meganewtons per square metre. The gold layer was adherent enough to withstand the water spray. Loss of gold was insignificant. The statues were then washed with nonionic detergent solution (Igepal CO 630), coated with an aqueous solution of benzotriazole (BTA) and finally covered with paste wax containing BTA.<sup>2</sup>

#### Inctalac: Product Description

Inctalac is an acrylic coating formulated for protection of copper and its alloys. It is based on Acryloid B-44 which is a copolymer of ethyl acrylate and methyl methacrylate, available as a 40% solution in toluene. Seventy-five parts of this solution is further diluted with 20 parts toluene and 5 parts ethanol. One half part each of benzotriazole and Paraplex G-60 are also added.<sup>3</sup> Benzotriazole is a chelating agent used as a corrosion inhibitor. It can function both to prevent corrosion of the metal, and to protect the Inctalac from the degrading effects of copper ions which diffuse into it. Paraplex G-60 is an epoxidized soybean oil used as a levelling agent. Inctalac is described in product literature as a hard, transparent acrylic having excellent resistance to ultraviolet light, which should last at least five years.<sup>3,4</sup>

#### Properties of Aged Inctalac

Infrared spectra of this aged and fresh Inctalac<sup>5</sup> are essentially the same. Their UV spectra, however, are quite different (Figure 3). The increased absorption of aged Inctalac could be due either to the

reaction products of degradation, or to absorption of UV absorbing pollutants from jet fuel or car exhausts, for example.

Assays by the Sherwin Williams Chemical Company, a manufacturer of BTA, found concentrations of BTA in the aged Inctalac samples of less than 0.1%. This is much less than the starting concentration of 1.5%.

We compared the solubilities of fresh Inctalac with those of aged Inctalac taken from a vertical, north facing section of the left rump of the horse of "Music and Harvest". The results are summarized in the following table. The aged Inctalac did not dissolve in any solvents. It did swell, however, in the solvents which most readily dissolved fresh Inctalac. Solubility tests were conducted according to the method described by McCrone.<sup>6</sup>

Solvent action on fresh and aged Inctalac

Solvent	Fresh		Aged
	insoluble	swells	insoluble
isooctane	x		x
propanol	x		x
N,N-dimethyl formamide	x		x
diacetone alcohol	x		x
turpentine	x		x
dimethyl sulfoxide	x		x
carbon disulfide	x		x
butanol	x		x
methyl cellosolve		x	x
methanol		x	x
cellosolve acetate		x	x
carbon tetrachloride		x	x
butyl acetate		x	x
methyl isobutyl ketone		x	x
1,1,1-trichloroethane		x	x
dioxane		x	x
ethanol		x	x
toluene		x	x
nitromethane		x	x
chlorobenzene		x	x
methyl ethyl ketone		x	x
ethylene dichloride		x	x
trichloroethylene		x	x
ethyl acetate		x	x
methylene chloride		x	x
acetone		x	x




Figure 3 Ultraviolet spectra of fresh and of weathered Inctalac.

#### Discussion

The Inctalac coating on these statues has failed as a coherent protective layer, and it has failed to remain soluble. The failure has not resulted in any major damage to the statues. Corrosion was not evident except at points such as soldered seams or casting pits where the nickel and gold plating was imperfect or at weep holes where corrosion products were washed out of the unplated interior. The plating withstood the harsh measures required to remove the insoluble Inctalac.

The failure of the Inctalac during ten years of outdoor exposure is not surprising. Inctalac product literature suggests a film life of at least five years. The increasing insolubility of Inctalac is also suggested by product literature ("In some instances it may be necessary to use a brass wire brush to loosen stubborn, old lacquer film."<sup>4</sup>), and it has been reported by Lafontaine.<sup>7</sup>

The infrared spectra indicate that there is little change in the type or number of functional groups as Inralac ages, which is why the solvents which swell the aged Inralac are solvents which also dissolve fresh Inralac. The insolubility is therefore probably due to crosslinking of polymer chains. Crosslinking of acrylics as a result of exposure to UV light is well known.<sup>8</sup> The acrylics commonly used in conservation are those which tend to crosslink most slowly, but one must keep in mind that insolubilization of Inralac will eventually occur.

The mechanical failure of the film may be due to thermal stress. The B-44 used to formulate Inralac is one of the harder acrylics, with a glass transition temperature of 60°C.<sup>3</sup> Below this temperature, B-44 becomes brittle and resistant to flow. Acrylics have a coefficient of thermal expansion about five times that of copper alloys.<sup>9</sup> Changes in temperature will cause differential contraction or expansion of Inralac and metal, and set up stresses within the Inralac. Crosslinking of the Inralac will make it even more brittle, and reduce its ability to relieve stress. Thermal extremes combined with crosslinking of the Inralac may eventually result in the mechanical failure observed.

#### References

1. F. Ogburn, E. Passaglia, H. C. Burnett, J. Kruger, and M. L. Picklesimer, Structural Repair and Surface Restoration of Four Twentieth Century Gilded Bronze Equestrian Statues, ICOM Conservation Committee, Report 2/27/6, 24 pp, 10 illus., 17 figs. (Madrid, 1972).  
  
F. Ogburn, E. Passaglia, H. C. Burnett, J. Kruger and M. L. Picklesimer, Restoration of Large Gilded Statues Using Various Electrical and Metallurgical Techniques, National Bureau of Standards Special Publication 479 (July 1977), from Superintendent of Documents, U.S. Government Printing Office, Washington, D.C. 20402.
2. N. Veloz, Selected problems in the preservation of outdoor sculpture, Bronze and Masonry in the Park Environment. Preprints of the conference cosponsored by the Center for Building Conservation, Central Park Conservancy, N.Y.
3. Acryloid Thermoplastic Acrylic Ester Resins, product information bulletin from Rohm and Haas, Philadelphia, Pennsylvania, 19105, U.S.A., 1976.
4. Technical Data Bulletin #581, A Superior Protective Coating for Copper, Brass, and Bronze, Maas and Waldstein Co., Newark, N.J., 07104, U.S.A.
5. Inralac supplied by Maas and Waldstein Co., Newark, N.J., 07104, U.S.A.
6. W. C. McCrone, A Rapid Solubility Test, paper presented at the IIC - American Group annual meeting, Philadelphia, 1965, and published in the International Institute for Conservation of Historic and Artistic Works American Group Bulletin 6(1), 1966.
7. R. H. Lafontaine, The Use of a Stabilizing Wax to Protect Brass and Bronze Artifacts, Journal of the IIC - Canadian Group, 4(2), 46-48, 1980.
8. See, for example, R. Feller, N. Stolow and E. H. Jones, On Picture Varnishes and Their Solvents, revised edition, The Press of Case Western Reserve University, Cleveland, 1971.
9. R. H. Perry and C. H. Chilton, eds., Chemical Engineer's Handbook, fifth edition, McGraw-Hill Book Company, New York, 1973.